

OUT54452

P 132153Z *Multi*
 FM NPIC WASHDC
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAA/2D RTS BARKSDALE AFB LA
 RUEAHQ/DIA WASHDC
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
 RUEPIA/CIA WASHDC
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
 RUWGAA/2AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 3282.

13 NOV 1964

HFS

WCB

GFC

DPS

ACL

-OPS FILES-

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 101 WAS USED IN MISSION 3965 FLOWN ON 12 NOVEMBER 1964; PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: MINUS DENSITY SPOTS SPACED 2.3" APART ARE LOCATED 1.00", 1.90", 1.91", 3.20", AND 5.20" FROM THE OUTBOARD EDGE OF THE FILM IN THE FIRST 50 FRAMES. OTHER RANDOMLY LOCATED MINUS DENSITY SPOTS ARE ALSO PRESENT IN THE FIRST 12 FRAMES. MANY SHORT, FINE, LONGITUDINAL PLUS DENSITY LINES ARE SCATTERED THROUGHOUT FRAMES 000 TO 900. A DIAGONAL PLUS DENSITY STREAK IS PRESENT IN FRAME 331, 335 AND 2506. LARGE AREAS OF THE FORMAT ARE FOGGED IN FRAMES 033, 60, 61, 114, 2514, AND 2515. A MANUFACTURING SPLICE IS PRESENT IN FRAME 513 WITH ASSOCIATED DENDRITIC STATIC DISCHARGES LOCATED 6.0" FROM THE TAKE-UP END OF FRAME 510.

C. 9L SIDE: MINOR ROLLER CHATTER OCCURS ALONG THE OUTBOARD

Declassification Review by NGA/DoD

EDGE FROM FRAME 000 TO 070. A MANUFACTURING SPLICE IS PRESENT ON FRAME 575.

D. BOTH SIDES: INBOARD AND OUTBOARD EDGE FOG OCCURS FROM THE BEGINNING TO THE END OF THE MISSION. INBOARD ROLLER CHATTER IS PRESENT IN THE FIRST 100 FRAMES. STATIC OCCURS ON THE INBOARD AND OUTBOARD EDGES WITH DECREASING INTENSITY THROUGHOUT THE MISSION. THE TITLED FRAME NUMBERS ARE FROM 0000 TO 2515.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS OBSCURED APPROXIMATELY 10 PERCENT OF THE MISSION.

GP-1

S E C R E T

--END OF MESSAGE--